

905-6780



**Ignition Switch  
INSTRUCTION SHEET  
for 430-662**

This ignition switch has a drain hole located on the threaded neck. This hole will permit water/moisture to enter the ignition switch if installed upside down.

If the switch is installed incorrectly (drain hole facing up) water cannot drain properly, ultimately failing the switch.

When installing ignition switch in instrument panel be sure drain hole on switch neck faces down.

