

# STIHL QUICK REFERENCE GUIDES

## REPLACEMENT PARTS FOR MS270 CHAINSAWS



### SABRE BARS

075-1606	Replaceable Sprocket Nose Bar	<b>16"</b>	<b>.325" Pitch</b>	<b>.063 Gauge</b>	<b>67 DL</b>
075-1806	Replaceable Sprocket Nose Bar	<b>18"</b>	<b>.325" Pitch</b>	<b>.063 Gauge</b>	<b>74 DL</b>
075-1816	Replaceable Sprocket Nose Bar	<b>18"</b>	<b>3/8" Pitch</b>	<b>.050 Gauge</b>	<b>66 DL</b>
075-2006	Replaceable Sprocket Nose Bar	<b>20"</b>	<b>.325" Pitch</b>	<b>.063 Gauge</b>	<b>81 DL</b>

### SABRE CHAIN

096-5676	Chain Loop Semi-Chisel	<b>.325" Pitch</b>	<b>.063 Gauge</b>	<b>67 DL</b>
096-5746	Chain Loop Semi-Chisel	<b>.325" Pitch</b>	<b>.063 Gauge</b>	<b>74 DL</b>
096-5816	Chain Loop Semi-Chisel	<b>.325" Pitch</b>	<b>.063 Gauge</b>	<b>81 DL</b>

STENS NO.	DESCRIPTION	REPLACES/SPECS
605-304	Air Filter	Stihl 1133 120 1604
705-224	Bar Guard	16"
705-222	Bar Guard	20"
635-293	Bar Nut (case of 2)	Stihl 0000 955 0801
630-107	Starter Pawl (case of 2)	Stihl 1125 195 7200
630-111	Spring Clip (case of 2)	Stihl 1128 195 3500
135-250	Spark Plug Boot	Stihl 1128 405 1000
635-250	Bumper Strip	Stihl 1121 648 6610
635-361	Chain Adjuster	Stihl 1125 007 1021
646-425	Clutch Assembly	Stihl 1121 160 2051
635-376	Torsion Spring	Stihl 1117 182 4500
635-055	Throttle Trigger	Stihl 1118 182 1006
635-428	Spr. Bearing	Stihl 9512 933 2260
085-0216	Sabre Rim Sprocket	.325" Pitch 7 Teeth Sm 7 Spline

STENS NO.	DESCRIPTION	REPLACES/SPECS
085-0706	Sabre Center Drive Spr.	.325" Pitch 7 Teeth
705-574	T-Wrench	3/4" x 1/2"
705-594	Torx T-Wrench	Stihl 4119 890 3400
705-194	T27 Power Bit 6"	Stihl 0812 540 1112
705-190	T27 Power Bit 3 1/2"	Stihl 0812 540 1112
610-254	Fuel Filter	Stihl 0000 350 3504
130-540	NGK Spark Plug	NGK BPMR7A
130-204	NGK Carded Spark Plug	NGK BPMR7A
130-013	Mega-Fire Spark Plug	Mega-Fire SE-BPMR7A
130-073	Champion Spark Plug	Champion RCJ6Y
130-124	Bosch Spark Plug	Bosch WSR6F
140-129	Starter Handle	Stihl 1121 195 3400
155-302	Starter Spring	Stihl 1129 190 0601